To: **TECHLAND**
#3-26
Juan-dong
Nam-gu
INCHEON
Korea

The following merchandise was submitted and identified by the client as :

Product Name	: Ceramic Coating Material
SGS File No.	: AYAA09-02719
Received Date	: February 02, 2009
Test Performing Date	: February 03, 2009
Test Performed	: SGS Testing Korea tested the sample(s) selected by applicant with following results
Test Results	: For further details, please refer to following page(s)
Buyer(s)	: CERASOL HK. LTD

SGS Testing Korea Co. Ltd.

Jeff Jang

Jeff Jang / Chemical Lab Mgr

Pluto Kim
Cindy Park
Jinee Song/ Testing Person

Sample No.	: AYAA09-02719.001
Sample Description	: Ceramic Coating Material
Item No./Part No.	: Ceramic Coating Material-Yellow
Comments	: Material is ceramics.

Polycyclic Aromatic Hydrocarbons

Test Items	Unit	Test Method	MDL	Results
Naphthalene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Acenaphthylene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Acenaphthene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Fluorene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Phenanthrene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Anthracene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Fluoranthene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Pyrene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Benzo(a)anthracene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Chrysene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Benzo(b)fluoranthene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Benzo(k)fluoranthene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Benzo(a)pyrene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Indeno(1,2,3-c,d)pyrene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Dibenzo(a,h)anthracene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.
Benzo(g,h,i)perylene	mg/kg	ZEK 01-08 , GC/MS	0.2	N.D.

NOTE:
   (1) N.D. = Not detected.(<MDL)
   (2) mg/kg = ppm
   (3) MDL = Method Detection Limit
   (4) - = No regulation
   (5) ** = Qualitative analysis (No Unit)
   (6) Negative = Undetectable / Positive = Detectable

SGS Testing Korea Co.,Ltd. | 322, The O valley, 555-9, Hogye-dong, Dongan-gu, Anyang-si, Gyeonggi-do, Korea 431-080
t +82 (0)31 4608 000 f +82 (0)31 4608 059 http://www.sgslab.co.kr ,www.kr.sgs.com/greenlab

Member of the SGS Group (Société Générale de Surveillance)

Picture of Sample as Received:

*** End ***

NOTE:

(1) N.D. = Not detected.(<MDL)
(2) mg/kg = ppm
(3) MDL = Method Detection Limit
(4) - = No regulation
(5) ** = Qualitative analysis (No Unit)
(6) Negative = Undetectable / Positive = Detectable

F052 Version3

SGS Testing Korea Co.,Ltd.

322, The O valley, 555-9, Hogye-dong, Dongan-gu, Anyang-si, Gyeonggi-do, Korea 431-080
t +82 (0)31 4608 000 **f** +82 (0)31 4608 059 http://www.sgslab.co.kr ,www.kr.sgs.com/greenlab

Member of the SGS Group (Société Générale de Surveillance)